Navajo Abandoned Uranium Mine

Site Screen Report

This form is for use at the site of abandoned uranium mines (AUM) located on Navajo Nation lands. Applicable sites include all mine and mine features that have or have not undergone reclamation by the Navajo Abandoned Mine Lands Reclamation Program, including features, adits, pits and waste piles. Applicable sites also include all AUM sites listed in the USEPA CERCLIS database, all sites listed in the 2008 AUM GIS Report issued by USACOE and USEPA, all AUM sites on allotment lands associated with the Navajo Nation, and any and all AUM sites not listed in any database located on Navajo lands. Reconnaissance of any sites located on lands adjacent to Navajo lands that may be impacting Navajo lands will need to be coordinated with the authorities appropriate to those lands.

The purpose of the form is to ascertain the status and location of the identified AUM site, and record all immediate site information associated with the mine site. Decisions and recommendations on what additional steps are needed will be provided on a separate document.

Mine Name: **Thomas No. 1**Mine ID: **290**

Navajo AUM Western Region

Prepared by:

Weston Solutions, Inc.

Contract: W91238-06-F-0083

20074.063.017.0020

August 2011

Part I	Site Identification, Location and Status				
Site Names ar	nd ID numbers	s as applicable	;		
Mine ID:	290				
Map ID:	W4				
CERCLIS:	NNN000909231				
Navajo Aban	doned Mine L	and Reclamati	ion Program: NA-0	259	
Local name /	Aliases: Thom	nas #1			
Chapter and	local area: Bo	odaway / Gap			
County: Coc	onino	State: Arizon	aa		
Lat/Long:	36.667359103	9 N / -111.639	811213 W		
Nearby road	and highway:	US-89	Local Post Office:	Tuba City, AZ	
Surface Land below	Status: check	one or more a	and provide ownersh	ip and contact information	
Tribal Trust ? Private Bureau of La State			Public lands Tribal Fee Land Allotment Fee land		
Subsurface M	Iineral Rights:	:			
No informatio	n on subsurface	e mineral rights	s ownership was found	in the EPA/AUM Database	
Claim and op	erator inform	ation:			

Number of residential structures within 200 feet of mine: None

The mine surface land status is classified as Tribal Trust Land. Historical documents identified the operator of the mine as F & B Mining in 1954, and Navajo Leytso from 1958 to 1960. No additional historical ownership / lease information was identified in the EPA / AUM database.

Part II Summary of Radiological Readings

Mine ID: 290

Highest gamma radiation measurement: 135,441 counts per minute (cpm)


Background Average: 7,676 cpm **Two Times Background:** 15,352 cpm

Describe any other radiological measurements:

A total of 4,570 gamma radiation measurements were collected from the mine site, ranging from 5,575 cpm to 135,441 cpm. Measurements collected in the vicinity of the test holes were found at a maximum level of approximately 135,000 cpm. The measurements are represented in Figures 1 and 2.

Distribution Chart and Statistics:

Site Gamma Radiation Statistics				
Number of Readings	4,570			
Minimum (cpm)	5,575			
Maximum (cpm)	135,441			
Mean (cpm)	21,496			
Median (cpm)	14,915			
Standard Deviation	16,066			



Part III Status of Reclamation and Mine Waste

Mine ID: 290

The following information was obtained from the Navajo Abandoned Mine Land Reclamation Program (NAMLRP) Point Features Database:

NAMLRP Status of the mine site: Reclaimed: Yes Waste Pile onsite: No

NAMLRP Project Number: NA-0259

NAMLRP Mine features: 1 Portal

The following information was obtained from field observations collected during the 2011 site screening:

Provide description and status of all mine sites and features at site. Include all waste piles, adits, pits and other features, and indicate whether they are open, closed, covered, capped, buried or unreclaimed. Indicate approximate size, shape and extent, including description of any reclamation caps. Note condition of all caps.

Observed reclamation work and status:

Adits:

Adit covered with red-rock boulders next to test holes

Waste Piles:

None observed

Pits:

None observed

Shafts:

None observed

Other Debris and Mine Features:

Test holes above outcrop; borehole; mining debris (wood, cables, tires)

Part IV Site Observations and Environs

Observed Residential Structures (number and human habitation status of structures at the following distances from the mine site):

0 to 200 feet: None observed

200 feet to 0.25 mile: None observed

Observed Public or Commercial Structures (schools, clinics, Chapter Houses, places of business and any other structures used by members of the community at the following distances from the mine site):

0 to 200 feet: None observed

200 feet to 0.25 mile: None observed

Levels measured around the perimeter(s) of the identified structure(s):

None

Observed Water Sources (number and type of wells and surface water sources that are potentially used for human consumption at the following distances from the mine site):

0 to 0.25 miles: None observed

0.25 miles to 4 miles: Bitter Springs approximately 2.5 mi SW of site

Sensitive Environments (all sensitive environments located within visible range of the mine site, including: wetlands, endangered species, habitats and approximate locations of sites that may be under protection of the government of the Navajo Nation):

None observed

Known Site History (information from interviews with Chapter officials and residents and database review, includes: mine ownership, type of mining operation, period of operation, known amount of production, and any other information provided):

The Thomas No. 1 mine claim consists of an area of 2,627.7 m². The mine was identified as being operational from 1954 to 1960. While operational, the mine had a total reported production volume of 154 tons. The mine surface land status is classified as Tribal Trust Land. Historical documents identified the operator of the mine as F & B Mining in 1954, and Navajo Leytso from 1958 to 1960. No additional historical ownership / lease information was identified in the EPA / AUM database.

Part V Response Action Summary

Summary of Evaluation Factors:

Accessibility:

Was the mine easily accessible to potential human activity?

Yes

Radiological Measurements:

Were any gamma radiation measurements collected at the mine greater than two times the site-specific background levels?

Yes

Waste Piles:

Were any unreclaimed waste piles observed at the mine with gamma radiation measurements greater than two times the site-specific background levels? No

Structures:

Were any structures observed within 200 feet of the mine?

No

Potential Drinking Water Sources:

Were any potential drinking water sources observed within 4 miles of the mine? Yes

Reclamation:

Was the mine reported to be previously reclaimed, or did the mine appear to be reclaimed?

Yes

Part VI Photos



Photo 1: Mine Site #290



Photo 2: Mine Site #290; Sealed adit



Photo 3: Mine Site #290; Test hole



Photo 4: Mine Site #290; Bore hole



Photo 5: Mine Site #290

Part VII Contacts Reports and Information

Name:	Eugene Esplain		
Title or official role (if any):	Navajo EPA Superfund Program		
Telephone number:	(928) 871-7331		
Address:	PO Box 2946, Window Rock, AZ 86515		
Information provided:	Lead Regulatory Agency		
N			
Name:			
Title or official role (if any):			
Telephone number:			
Address:			
Information provided:			
N			
Name:			
Title or official role (if any):			
Telephone number:			
Address:			
Information provided:			

Figure 1 - Gamma Radiation Measurements, Above Two Times Background
Thomas No. 1 (290)
Bodaway / Gap Chapter, Navajo Nation





Figure 2 - Gamma Radiation Measurements Thomas No. 1 (290) **Bodaway / Gap Chapter, Navajo Nation**




- 0 10,000 cpm
- 10,000 25,000 cpm
- 25,000 50,000 cpm
- 50,000 100,000 cpm
- 100,000 250,000 cpm
- 250,000 500,000 cpm
- 500,000 1,000,000 cpm

Measured as counts per minute (cpm) Average background 7,676 cpm





Observed Reclamation Feature



Observed Structure

Steep Grade

Observed Adit









